

Approved For Release 2000/06/14 : CIA-RDP78-06505A000700100002-7

ADVANCE COPY ☐ ISSUED ☐ SLOTTED

REPRODUCTION OF THIS COPY PROHIBITED

2	6
3	7
4	8

MAR 19 7 40 AM '71
ACTION COPY

EXEMPT BY 48 PER

ACTION UNIT

ACTION NO. 257

FILE, VR

FE4

SECRET 190709Z MAR 71 CITE [REDACTED] 15843

25X1A

DIRECTOR

25X1A

[REDACTED] DTD 5 FEB 71 RE

19 MAR IN 291006

1. ACCORDING TO OUR BEST ESTIMATES ABOUT \$800 WORTH OF NEW PARTS ARE NEEDED RIGHT NOW TO KEEP THE CURRENT AIR CONDITIONING SYSTEM IN OPERATION. WITH LUCK IT MAY LAST FOR YOUR SPECIFIED FOUR YEAR PERIOD BUT OF COURSE WE CAN'T GIVE ANY GUARANTEES.

2. ALSO, WE ESTIMATE THAT IT WILL COST US ABOUT \$1200 TO MAINTAIN THE OLD SYSTEM OVER THE SAME FOUR YEAR PERIOD WHEREAS THE NEW ONE WOULD RUN ABOUT \$500.

3. COSTS OF LABOR ARE NOT INCLUDED IN THE ABOVE FIGURES.

4. EVEN THOUGH A NEW SYSTEM WOULD BE THE IDEAL ANSWER, IN VIEW OF THE "IFFINESS" IN OUR CURRENT SITUATION, WE WILL IMPLEMENT YOUR RECOMMENDATION TO PATCH AND REPAIR. GP-1.

SECRET

RECD

3 AC/SEC
JL 3/22/71
EX 3/13/71
SA

C/REB

RO

C/REB

PE

C/REB

PE

FILE

25X1A

Hal:
Please relate this
to something from
up

SECRET